

Commercial Vehicle Enforcement

NORTHEAST SECTOR:

Details:

- 12/07 Coventry Rest Area, I 91 South. Four Inspectors screened 122 vehicles. Sixteen inspections were completed. Seven vehicle (one out of service) and six driver (one out of service) violations were discovered.

NOTABLES:

- 12/05 Newport, VT Rte 105. An Inspector stopped a CMV for a permit violation- the over dimension CMV was missing a required flag. An inspection was completed and the violation was repaired on scene.



- 12/07 Coventry detail. An Inspector grounded a CMV for the motor carrier being under suspension in VT for failure to return an inspection violation. An inspection was completed.



- 12/05 Derby, Vt Rte 111. An Inspector conducted a portable weigh on a CMV. The CMV was found to be 13,900 lbs over its registered weight. A ticket was issued to the company.
- 12/05 Brownington, Old Stonehouse Rd. Inspectors were dispatched to a CMV pulling doubles that was stuck on an inclined roadway. The carrier was discovered to have no permit and was educated on operations of doubles in VT. An inspection was completed and the CMV was placed out of service for 20% or more of the service brakes on the combination was defective.



- 12/06 Coventry, Us Rte 5. An Inspector conducted an inspection on a CMV and discovered the operator's CDL was disqualified for not having a valid medical certificate. The driver was placed out of service.



- 12/07 Coventry detail. An Inspector conducted an inspection on a CMV and discovered the carrier was suspended in The State of VT and had an active leak from the saddle tank out of the bottom fitting. The vehicle was placed out of service.



- 12/08 Enosburg. A CMV was stopped and weighed. The CMV was registered for 26,000lbs and weighed 33,900lbs. The driver did not possess a Class B CDL as required. An inspection was completed and the driver was placed out of service for not possessing a CDL.



Details:

- 12/5, Putney Scale House I-91 S. Three inspectors screened 142 vehicles resulting in 6 inspections. There were 7 vehicle violations and 4 driver violations. One driver and one vehicle were placed out of service.



- 12/7, Springfield NB I-91. Three inspectors screened 142 vehicles resulting in 6 inspections, no violations were detected.

Notables:

- 12/4, Inspector stopped a 3-axle dump truck hauling gravel on US 7 in Dorset. A level 2 inspection revealed the truck was overweight and had an expired permit. The vehicle registration was also expired. The truck was only good for 55,000lbs and had a scale weight of 65,160. The carrier was issued a VCVC for the violation and called DMV to obtain a valid registration and permit.



- 12/4, Inspector stopped a passenger car on Interstate 89 S in the Town of Randolph for speeding. The vehicle was travelling 114 MPH in a posted 65 MPH zone. The operator was issued a VCVC.

- 12/6, Inspector stopped a log truck on I 89 N at the Randolph Rest Area. During the inspection a flat tire, inoperable turn signals on the trailer, and a corrosion gap greater than 1/8 inch was found on the upper fifth wheel plate. The vehicle was placed out of service.



- 11/30 Inspector attended a CVSA webinar on WIMS (weighing in motion) technology.
- 12/5 Inspector discovered a defective tire during an inspection at the Putney Scale House.

Commercial Vehicle Enforcement

NORTHWEST SECTOR:

Details:

- 12/5 Ira Rest Area, Rte. 4, 3 Inspectors screened 89 vehicles. 7 inspections were completed which resulted in 18 vehicle violations and 7 driver violations. Two vehicles and one driver were placed out of service.
- 12/5 Williston Rest Area, I 89 N, 4 Inspectors screened 278 vehicles. 9 inspections were completed which resulted in 18 vehicle violations and 3 driver violations. Four vehicles and one driver were placed out of service.
- 12/7 Georgia Rest Area, I 89 S, 8 Inspectors screened 189 vehicles. 11 inspections were completed which resulted in 19 vehicle violations and 4 driver violations. Three vehicles were placed out of service.

Notables:

- 12/4 Cpl. stopped a truck hauling an equipment trailer on I 89 in Richmond. An inspection was conducted, and it was determined the driver did not have a CDL. The combination required a CDL and the trailer was missing its emergency breakaway device. A check of the trailer's VIN revealed it was reported stolen from Chittenden County in early 2023. The trailer was seized as evidence in an ongoing investigation. The company, a licensed used car dealer, was issued

multiple tickets.



- 12/5 Insp. conducted supervised level 1 inspections at the Ira detail. Two vehicles were placed out of service for air leaks and defective brake systems.
- 12/5 Insp. and Cpl. conducted a portable weigh on an oversize load. The load weighed 132,000 and there was no permit in place, as the company claimed emergency exemption due to flood assistance. The vehicle was allowed to return to its terminal.



- 12/5 Cpl. inspected an interstate tractor trailer hauling hazardous materials at the Williston detail. The vehicle was placed out of service for failing to have hazmat shipping papers.



- 12/5 Cpl. inspected an intrastate truck and trailer at the Williston detail. The trailer was placed out of service for failing to flag a projecting load.



- 12/7 Insp. conducted supervised level 1 inspections at the Georgia detail. A truck was placed out of service for defective brakes and no operative brake lamps on the rearmost vehicle.
- 12/7 Insp. while conducting a Level 1 inspection at the Georgia detail, located a 4 ½ inch cracked brake pad on the steer axle. The vehicle was placed out of service.



- 12/7 Cpl. inspected an interstate tractor trailer at the Georgia detail. The trailer was placed out of service for an inoperable turn signal.

