

Commercial Vehicle Enforcement Unit

NORTHEAST SECTOR:

Details:

- 03/28, WRJ Rest Area, I 91 North. Five Inspectors screened 276 vehicles. Twenty-three inspections were completed. Thirty-nine vehicle (four out of service) and six driver (one out of service) violations were discovered.
- 03//30, Barton Rest Area, I 91 North. Three Inspectors screened 118 vehicles. Twenty inspections were completed. Three vehicle and one driver violations were discovered.

Crashes:

- None reported.

Notables:

- 03/27, Morrisville Rte 100. An Inspector was on patrol in the Morrisville area and heard a BOL for a dump truck. The dump truck was losing construction debris from the dump body which had damaged a vehicle which was following it. A traffic stop was initiated, an inspection was completed and the CMV was placed OOS for the load securement violation. A VCVC was issued and the Morrisville Police department facilitated the exchange of insurance information for the vehicle which was damaged.
- 03/28 WRJ detail. An Inspector conducting a Level 1 inspection placed a CMV OOS for greater than 20% of its brakes being beyond adjustment limits.
- 03/28 WRJ detail. An Inspector conducting an inspection on a CMV placed it OOS for having an inoperable parking brake and a defective emergency break away cable. The carrier was assessed a violation for being engaged in Interstate commerce without being assigned a USDOT number and the driver was assessed a violation for not having a medical card.
- 03/28 Lunenburg, US Rte 2. Inspector Jacobs and Hailey and their K9 partners were asked to assist the Essex County Sheriff's Department to track a subject who was the subject of a welfare check. The subject was located deceased prior to the teams arrival.
- 03/28, WRJ detail. An Inspector conducting a Level 2 inspection placed the CMV out of service in combination for a defective trailer air brake supply hose.



- 03/31Granville. An Inspector on patrol stopped a four-axle log truck for improper load securement. An inspection was completed and the CMV was placed out of service.



- 03/31 Hartford, US Rte 5. An Inspector on patrol stopped a dump truck for defective lamps. An inspection was completed and the CMV was placed out of service for an inoperative turn signal at the rear of the vehicle.

